

Needle bearing

2311091



Needle bearing 10X32X17

If the rear wheel has too much play, the needle bearings are usually broken.

It is recommended to replace both bearings.

Compare BMW article numbers 33172311091.

Art-Nr.: 2311091

82,90 EUR

Needle bearing 10X32X17 (1 piece)

Additional pictures:

