

Lambda sensor

11781341022QT



Lambda sensor

BMW R1150GS & Adventure

BMW R850R (2002-), R1150R & R1150R Rockster

BMW R850RT (2002-) & R1150RT

BMW R1150RS

BMW R1100S

BMW R850C, R1200C (-2002), R1200C Independent (-2002)

BMW R1200CL

BMW K1200RS (-2000)

Compare original BMW part no. 11781341022.

Attention: Once the parts have been installed, they cannot be returned!

Art-Nr.: 11781341022QT

84,90 EUR

Lambda sensor